

C/109

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No: F.6/DFS/MS/School/2023/WZ/ 37

Dated: 23/01/2023

To,

The Principal,
M C Primary Girls School,
Mungeshpur, Delhi-110039.

Sub: - Regarding issuance of Fire Safety Certificate in r/o M C Primary Girls School (New Building) ID No. 1355022, Mungeshpur, Delhi-110039.

Sir,

This has reference to your mail id dated 07.01.2023 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 12.01.2023 to see the compliance of the requisite fire safety measures. Sh. Virender Singh (Attendant) was present at the time of inspection. During the course of inspection it was observed that school building was comprised of Ground floor plus one upper floor. Your request of issue of FSC is rejected as the following shortcoming was observed:-

1. Gate width found 4.30 m against the required clear width of 4.50 m.
2. Electric panel box was found installed under the staircase which has to be removed from that location.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for issuance of Fire Safety Certificate.

Yours Faithfully

(Atul Garg)

Director

Delhi Fire Service

our

Copy to:-

1. Director of Education, NDMC, Civic Center, New Delhi.
2. Executive Engineer (Project) , Narela Zone, Zonal Office Building, Narela , New Delhi-10006.