



75  
Azadi Ka  
Amrit Mahotsav

C/36

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE  
NEW DELHI- 110001**

No. F.6/DFS/MS/School/2023/NDZ/ 66

Dated: 06/02/2023

To,

The Principal,  
Shri Sanatan Dharam Middle School  
Shri Raghunath Mandir, Krishan Nagar, (Ghondli) Delhi- 110051

**Sub:- Regarding Issuance Fire Safety Certificate r/o Shri Sanatan Dharam Middle School located at Shri Raghunath Mandir, Krishan Nagar, (Ghondli) Delhi- 110051.**

Sir,

This is in reference to your letter No. RG/MS/913/2022-23 dated 21/12/2022 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned School from fire safety point of view on dated 19/01/2023 in presence of Mrs. Meenu Sharma, Principal of the School. The following points / shortcomings were noticed in the building which is comprised of ground plus two upper floors.

1. First-Aid hose reels provided but not functional.
2. Fire pump having 450 LPM output with 40 meter head not provided.
3. Overhead water storage tank capacity 2,500 liters is provided against requirement of 10,000 liters.
4. Exit signages not provided.

In view of above, the building can not be considered for grant of fire safety certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully

  
03/02/23  
(S.K. DUA)

**DY. CHIEF FIRE OFFICER  
DELHI FIRE SERVICE**

o/c 2

Copy to:-

The Dy. Director of Education,  
D-Block Anand Vihar, Delhi-110092