



7.3  
C/77

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No. F6/DFS/MS/School/2023/NDZ/ 137

Dated: 23/03/2023

To

The Executive Engineer(E),  
DTTDC Ltd., Srinivaspuri, Lajpat Nagar,  
Near Cambridge School, Ring Road, New Delhi-110065.

Subject:- Regarding issued of "Fire Safety Certificate" from fire safety point of view in r/o Rajkiya Sarvodaya Kanya Vidyalaya, Block-27, Trilokpuri, Delhi-110091.

Sir,

This has a reference to your letter No. 23(03)/DTTDC/Engg./EE(E)/2022-23/453 dated 02/12/2022, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 10/03/2023 in the presence of Sh. Nirdosh Kumar (Estate Manager) and observed that building comprised of A & B Block-Ground & Two Upper Floors & C and primary Block-Ground & One Upper Floor only.

Following shortcomings were observed during time of inspection :

1. An additional staircase having width of 1.50 mtr shall be required in A, B & C block.
2. Over Head Tank capacity of 10,000 ltr not provided in B-Block.
3. Exit Signage's not provided.

Keeping in view of above shortcomings, the application for issuance of Fire Safety Certificate cannot be considered at this stage. You are requested to rectified above mentioned shortcomings under intimation to this department for taking necessary action in this matter.

Yours faithfully,

  
(ATUL GARG)  
DIRECTOR  
DELHI FIRE SERVICE

Copy to:-

1. The Principal, Rajkiya Sarvodaya Kanya Vidyalaya, Block-27, Trilokpuri, Delhi-110091.
2. The Dy. Director of Education, D-Block, Anand Vihar, Delhi-110092.