



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No. F6/DFS/MS/2023/NDZ/ 147

Dated: 23 / 03 / 2023

To

Sh. Rohit Dhingra,  
Rockers and Shockers Pvt. Ltd., Shop No.-20,  
2<sup>nd</sup> Floor, Star City Mall, Mayur Vihar, Delhi-110091.

Sub.: Inspection Report in r/o Rockers and Shockers Pvt. Ltd., Shop No.-20, 2<sup>nd</sup> Floor, Star City Mall, Mayur Vihar, Delhi-110091.

Sir,

With reference to your MHA portal application No. 2022121621421 Dated 09/01/2023 on the subject noted above. In this connection it is to inform you that the said building premises was inspected by the officers concerned of this department on 04.03.2023 in the presence of Sh. Ankit and following shortcomings were observed during the time of inspection:-

1. 2 Doors of width 1.00 m are provided against requirement of 1.50 m width each.
2. 2<sup>nd</sup> door (Back Side) is passing through kitchen and service lane and also far away from the staircase.
3. Fire Check door not provided in kitchen.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

  
(ATUL GARG)

DIRECTOR  
DELHI FIRE SERVICE.

Copy to:-

1. The Joint Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-24 w.e.f. MHA Portal Application No. 2022121621421 dated 09/01/2023.