



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F-6/DFS/MS/2023/Gym/ 625
To

Dated 27/03/2023

Sh. Anand Shukhla
Property No. 2448/49, Ground Floor,
Punjabi Basti, Tikona Park, Malka Ganj,
Delhi-110007.

Sub: - Regarding issuance of fire safety certificate in r/o M/s Wisdom Gym at Property No. 2448/49, Ground Floor, Punjabi Basti, Tikona Park, Malka Ganj, Delhi-110007.

Sir,

This has reference to letter no. nil dated 07.02.2023 on the subject cited above. In this connection this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 09.03.2023 in the presence of Mr. Anand Shukhla to verify the fire safety arrangements as stipulated in NBC Part 4 and as well installed in the building. During the course of inspection it has observed that the building/ premise is comprised of ground & 03 upper floors but (Gym at ground floor only). Your request for FSC is rejected under Rule 35 (3) due to following shortcomings.

- 1 There are two exit doors having width of 1.40m, & 1.10m provided against requirements of 02m & 1.50m .
- 2 Smoke ventilation system not provided.
- 3 Hose reel hose provided but not functional.
- 4 MOEFA system not provided.
- 5 Internal hydrants not provided.
- 6 Terrace pumps capacity of 450lpm not provided.
- 7 Terrace level fire water tank capacity of 20,000ltrs is not provided.
- 8 Exit signage's not provided in the gym.
- 9 Standby power supply not provided.

Keeping in view of above Fire Safety Certificate cannot be considered at this stage. You may apply again on form 'I' as stipulated in sub rule (2) 35 of rules, DFS Rules 2010 after compliance of the shortcoming mention above. The link for forms is as under available on <http://delhi.gov.in/wps/wcm/connect/doitfire/FIRE/Home/Forms>.

Yours faithfully

(Atul Garg)
Director

Ph: 011-23414000

Copy to:

1. The Dy. Health Officer, Municipal Corporation of Delhi., 16, Rajpura Road, Delhi-110054.