



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001 Dated: 06 04 2023

No. F6/DFS/MS/WZ/2023/697

To

The Authorized sigantory, Shivam House, B-2, karampura Comm. Complex, New Delhi -110015.

Sub: - Inspection report in r/o M/s Shivam House Locate at B-2, karampura Comm. Complex, New Delhi -110015.

Sir,

Please refer to your letter received through outdoor diary no. 11911 dated 03/03/2023 on the subject cited above. In this connection, it is to inform you that the premises/Building was inspected by the officer concerned by this department on 20/03/2023 in the presence of Sh. Amrik Singh to check the shortcomings already issued vide letter no. F6/DFS/MS/WZ/2023/150 dated 25/01/2023.

The Status of the Shortcoming is as under:-

| S. no. | Shortcomings  | Status        |
|--------|---|---------------|
| 1.     | Fire Check Doors are found removed at some places.  | Not Rectified |
| 2.     | First Aid hose reel provided but not functional.  | Not Rectified |
| 3.     | Automatic fire detection and alarming system provided but not functional.                     | Not Rectified |
| 4.     | MOEFA is provided but not functional.   | Not Rectified |
| 5.     | Public address system provided but not functional.  | Rectified     |
| 6.     | Automatic sprinklers system is provided but not functional.                                   | Not Rectified |
| 7.     | Internal Hydrants is provided but not functional.   | Not Rectified |
| 8.     | Main Pump 900 lpm is found removed.   | Not Rectified |
| 9.     | Overhead water storage tank capacity 50,000 ltrs are provided but uses as a domestic purpose. | Not Rectified |
| 10.    | Exit sinages found removed.   | Not Rectified |

In view of above, application for renewal of Fire safety Certificate is rejected. The occupancy of the Building/ premises in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/occupier. The licensing issuing authority/statutory authority is requested that premises should not be allowed to run till it provide all necessary fire arrangements.

Yours faithfull

Copy To: -

1. The Executive Engineer (Building), MCD, Karol Bagh Zone, Anand Parbat, New Delhi. (Email Id: - eepwddelhim132@gmail.com)