



7.03/23  
C/23

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No. F6/DFS/MS/School/2023/NDZ/ 142

Dated: 27/03/2023

To

The Principal,  
Shishu Bharti Shiv Mandir Vidyalaya,  
Vishwakarma Nagar, Jhilmil, Delhi-110095.

Subject:- Regarding issued of "Fire Safety Certificate" from fire safety point of view in r/o Shishu Bharti Shiv Mandir Vidyalaya, Vishwakarma Nagar, Jhilmil, Delhi-110095.

Sir,

This has a reference to your letter No. SBSM/036/2023 Dated 09/03/2023, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 20/03/2023 in the presence of Smt. Vidushi Sharma (Principal) and observed that building comprised of Ground & Two Upper Floors only.

Following shortcoming were observed during time of inspection :

1. Width of staircases are 1.10 meter & 1.05 meter, against required width of 1.5 meter each. Further second staircase is also not going to terrace (It is terminating in one of the rooms on second floor which is used by chowkidaar and that room is not having access to terrace).

Keeping in view of above shortcomings, the application for issuance of Fire Safety Certificate cannot be considered at this stage. You are requested to rectified above mentioned shortcomings under intimation to this department for taking necessary action in this matter.

Yours faithfully,

(ATUL GARG)  
DIRECTOR  
DELHI FIRE SERVICE

o/c/AB