



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No. F6/DFS/MS/SCHOOL/WZ/2023/186

Dated: 17/04/23

To

The Principal,  
Kapila Public School,  
02, Sandesh Vihar, Pitampura  
New Delhi- 110034.

**Sub: - Regarding issuance of Fire Safety Certificate in r/o Kapila Public School,**  
**Located at 02 Sandesh Vihar, Pitampura, New Delhi – 110034.**

Sir,


Please refer to your Letter no. KPS/MCD/FIRE/07/23 dated: - 06/03/2023 on the subject cited above. In this connection, it is to inform you that the aforesaid school building have been re-inspected by the officer concerned of this department on 29/03/2023 in presence of Smt. Poonam Wadhawan (Principal) to check the shortcoming already issued by this department vide letter no. F.6/DFS/MS/School/WZ/2022/220 dated 13/05/2022.

The Status of shortcomings are as under:-

S. no.	Shortcomings	Status
1.	One additional staircase having width atleast 0.75mt is required.	Not Rectified
2.	Terrace pump is provided but not functional.	Not Rectified
3.	Hose reel hose is provided but not functional.	Not Rectified
4.	capacity of overhead water tank is less than required capacity of 2500 ltr.	Not Rectified

In view of above shortcomings the application for issuance of Fire Safety Certificate is rejected. The occupancy of the Building/ premises in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/occupier. The statutory authority is requested that premises should not be allowed to run till it provide all necessary fire arrangements.

Yours faithfully

  
(Atul Garg)  
Director  
13/4/2023

Copy To: -

1. The Director, Directorate of Education, old secretariat, Delhi.