

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

NO. F-6/DFS/MS/School/2023/WZ/ 192

Dated: 18/04/23

To,

Er. Shashank Sahu,  
Assistant Engineer (E), PWD, Sub-Division-2,  
Edu. Elect. Edn. 1, Div. (N)  
Sector-16, Rohini, Delhi-110089.

**Sub: - Regarding Fire Safety Certificate in r/o Govt. Sr. Sec School UK-SKV Dariyapur Kalan , Auchandi Road, Delhi-110039.**

Sir,

This has reference to your application received through email id dated 20.03.2023, on the subject cited above, it is to inform you that above mentioned school building was visited by officer concerned of this department on 11.04.2023 in presence of Sh. Anshul (Electrical Engineer). During course of inspection it is observed that school building comprised of Ground and Three Upper Floors. Your request for issuance of Fire Safety Certificate is rejected as following shortcomings were observed.

1. Fire Extinguishers not provided.
2. First Aid Hose Reels provided but not functional.
3. Terrace level pump provided but not functional.
4. Exit signage's not provided.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for issuance of Fire Safety Certificate.

Yours faithfully

(Atul Garg)  
Director

Ph. 011-23414000