

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No.F6/DFS/MS/School/SZ/2023/ 239

Dated:

09 05/2023

To

The Principal, Good Samaritan School, B-100 (Old No.), B-125 (New No.), Madanpur Khadar Extn.-II, Kanchan Kunj, New Delhi-76.

Regarding renewal of Fire Safety Certificate in respect of Good Samaritan School located Sub:at B-100 (Old No.), B-125 (New No.), Madanpur Khadar Extn.-II, Kanchan Kunj, New Delhi-76.

Sir,

With reference to outdoor diary no. 988 dated 21.04.2023 on the subject cited above, it is informed that the school building was inspected by Assistant Divisional Officer (M. Road) from this department on 28.04.2023 in the presence of Mr. Chakkaravarthi (Maintenances) and it was observed that the building which was earlier comprised of ground floor only is now comprised of 2 blocks (A block- Ground + 02 upper floors & B block Basement + ground + 04 upper floors). Hence is a case addition/alteration. During the inspection following shortcomings were observed:-

- 1. Staircase width of 1.50 meters each must be provided.
- 06 nos. fire extinguishers provided against the requirement of 25 nos. fire extinguishers.
- 3. Hose reel not provided in each block.
- 4. Fire pump having capacity 450 LPM & head 40 mtrs. not provided in each block.
- 5. Overhand tank capacity 10,000 ltrs not provided in each block for fire fighting.
- Exit signages not provided.
- 2 nos. of staircases continuous to terrace must be provided in B block.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully Director Delhi Fire Service Ac Chis

Copy to:-.

The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, 1. New Delhi-24.