



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/School/2023/WZ/ 238

Dated:- 09/05/2023

To,

The Principal,  
St. Mark's Senior Secondary Public School,  
A-Block, Meera Bagh, New Delhi-110087.

**Subj:- Regarding issuance of Fire Safety Certificate in respect of St. Mark's Senior Secondary Public School Located at A-Block, Meera Bagh, New Delhi-110087.**

Sir,


This has reference to your form '1' dated 13.04.2022 on the subject cited above. In this connection, it is to inform you that the said school building was re-inspected by the officers concerned of this department on 29.04.2023 in the presence of Sh. Rahul Aggarwal (Director), to check the shortcomings issued by this department vide letter no. F6/DFS/MS/2022/WZ/School/662 dated 27.10.2022.

During the course of inspection, it has been observed that the Management has rectified some of the shortcomings, the status is under:-


S. no.	Shortcomings	Status
1.	The width of internal road 06 m is not provided	Not yet rectified
2.	Fire check door is not provided in staircase & lift lobbies	Not yet rectified
3.	Pressurization system in staircase and lift lobbies is not provided	Not yet rectified
4.	One additional staircase having width minimum 1.5 mts as mentioned in sanctioned plan, is not provided	Rectified
5.	Exit signages are not provided	Not yet rectified

In view of the above shortcoming, the application for renewal of Fire Safety Certificate is not considered & rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,

  
(Anil Garodia)  
Director  
Delhi Fire Service

Delhi Fire Service

  
09/05/23

Copy to:-

1. The Executive Engineer (Bldg.), Municipal Corporation of Delhi, 8<sup>th</sup> floor, Civic Centre, Minto Road, New Delhi.