

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No: F.6/DFS/MS/School/WZ/2023/246

Dated: (5/05/2023

To

The Assistant Engineer (E), Sub-Division 2, Edu. Elect. Edn. I Div (N), PWD, Dr. K.N. Katju Marg, Shaheed Sukhdev College Campus, Sector-16, Rohini, New Delhi- 110089.

Sub.:- Regarding issuance of Fire Safety Certificate in r/o New Block at Govt. Girls Sr. Sec. School, Rani Bagh, Delhi- 110034.

Sir.

This is in reference to your letter No. 54(11)/AE(E)-2/Edu.Elect.Edn.1 Div.(N)/2022-23/17 dated 25.03.2023 received through e-mail ID aee2pwdedum1@gmail.com dated 27.03.2023 on the subject cited above. In this connection, it is to inform you that the school building was inspected by the officer concerned of this department on 08.05.2023 to check the letter vide department this shortcomings issued by the F6/DFS//MS/School/WZ/2023/33 dated 19.01.2023, and status is as under: -

S No	Shortcomings	Status
1.		Found functiona
2.	Hose reel hose, down comer are provided but not functional.	Fund functional
3.	Exit signages are not provided at some places.	Found provided
4.	Width of exits in M.P. hall is less than required width of 2.0 mts each.	Not Rectified

In view of the above shortcoming at Sr. No. 04, the request for issuance of fire safety certificate cannot be considered at this stage & rejected. You are advised to rectify the above mentioned shortcoming under intimation to this department for further necessary action in this regard.

Yours faithfully

Copy to: -

- The Principal, Govt. Girls Sr. Sec. School, Rani Bagh, Delhi- 110034.
- The Directorate of Education, GNCT of Delhi, Old Secretariat, Delhi- 110054.