

C-3

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No: F.6/DFS/MS/School/2023/WZ/282

Dated: 30/05/2023

To,

The Principal,
Roxfield Public School,
230, Kh. No. 199,
Auchandi Road, Bawana,
Delhi-110039.

Sub: - Regarding issuance of Fire Safety Certificate in r/o Roxfield Public School,
230, Kh. No. 199, Auchandi Road, Bawana, Delhi-110039.

Sir,


This has reference to your letter no. nil received via outdoor diary no. 1689 dated 04.05.2023 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by the officer concerned of this department on 11.05.2023 to see the compliance of the requisite fire safety measures. Sh. Gajender Kumar was present at the time of inspection.

During the course of inspection it was observed that school building comprised of Ground and First Floor. Your request for issuance of FSC is rejected due to the following shortcomings:-

1. Width of staircase found 1.10 m & 1 m provided against the required width of 1.50 m each.
2. Door width provided 1 m against the required width of 1.20 m.
3. Building plans on a scale of 1:100 duly signed by registered architect and the owner not provided.


You are advised to rectify the above-mentioned shortcoming under intimation to this department.

Yours Faithfully


(Atul Garg)

Director

Ph. 011-23414000



Copy to:-

1. Director of Education, Govt. Of NCT of Delhi, Old Secretariat, New Delhi.