



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001 Dated 0 5 10 G /2023

F.6/DFS/MS/2023/SZ/ 17-5 No.

To

Mr. Rajesh Soni, OM Apartments Pvt Ltd., Deepalt Building, 92, Nehru Place, New Delhi 110019.

Sub: Regarding Renewal of Fire Safety Certificate in r/o M/s Deepali Building, 92, Nehru Place, New Delhi 110019

This has reference with your letter received through outdoor diary no 1578 Dated 02-05-2023 on the subject cited above. In this concretion it is to inform you that the premise was inspected by the concern officers of this department on 28-05-2023 & observed that the building is comprised of Basement, and Eight upper floors. During the course of inspection, the following shortcoming observed were noticed -

2. Sealing of electrical / plumbing shaft are not sealed for proper Compartmentation/ segregation.

Automatic sprinkler system provided but found not functional.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Copy to: -

1. The Executive Engineer (Bldg) South MCD, Dr. SPM Civic Center, Minto Road, New Delhi 110002