

C-101

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

No. F6/DFS/MS/Hospital/NDZ/2023/1249

Dated 16/06/2023

To

Sh. Surender Sharma,
Vice President Sant Parmanand Hospital,
Plot no. 1, 2 & 3, Jamuna Bazar, New Delhi.

**Sub: Regarding issuance of Fire Safety Certificate in r/o Sant Parmanand Hospital Building,
Plot no. 1, 2 & 3, Jamuna Bazar, New Delhi.**

Sir,

This has reference to outdoor diary no. 1964 dated on 15.05.2023 on the subject cited above. In this connection this is to inform you that the above said hospital was inspected by the officers concerned of this department on 08.06.2023 in the presence of Mr. Hari (Admin officer) and it was observed that the building is comprised of 3 Basement + 9 upper floors (including ground & service floor). During inspection the following shortcomings were observed:

1. Pressurization system for lift lobbies and staircase not provided
2. Sealing of all electrical shafts (horizontal & vertically) not done.
3. Water curtain in front of Car lift not functional properly at basement level.
4. Detection system should also be extended in all electrical shafts.
5. Access ladder for overhead water tank should be installed at terrace level.
6. Exit/Lift Signages are not provided completely.
7. Lift lobby encroached at some floors.
8. UPS/ Server room should be protected with Automatic total flooding system.
9. Sprinkler should be extended in all left out areas.
10. Basement entry should be segregated at ground floor level.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The applicant is requested to rectify the shortcomings at the earliest for further action.

Yours faithfully,


(Atul Garg)

Director

Delhi Fire Service o/c
Tel:-011-23414000

84
16/6