GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F6/DFS/MS/NDZ/Hosp/2023/ 1) 5 o

Dated 16 /06/2023

To,

The Executive Engineer (E), PWD. HMED (Central). Lok Nayak Hospital, New Delhi - 02.

Sub:- Inspection of all major hospitals from fire safety point of view .

This has reference to the directions issued by The Chief Secretary, Govt. Of NCT of Delhi on the subject cited above. In this regard, it is to inform you that the 02 block of LNJP hospital were inspected by the officers concerned of this department on 09.06.2023 in the presence of Sh. S.C Das AE (E) & JE (E), PWD& and the following shortcoming were still not complied :-

A. Causality , OPD and surgical block.

1. 06 meter road for fire tender movement all around the said block is not provided Clearly.

2. One staircase of surgical block found blocked by dumping of waste items/ materials, which may leads to obstacle/hurdle to evacuate of the occupants/patients of the surgical block at the time of emergency

3. Detectors found non-functional in the basement and some places at upper floors

4. Ramp serving to upper floors of surgical block found locked

Hose Reel & hydrants found non-functional in surgical block.

Smoke management system in basement found non functional. Exit signage's found inadequate, required to be provided at conspicuous places.

8. Electrical shafts are not sealed horizontally & vertically.

Good housekeeping shall be ensured in all blocks.

Causality block is under renovation.

B. Ortho Block:

 06 meter road all around the building for fire tender movement found encroached with parking, shed and tree branches.

2. Fire check door needs to be repaired /replaced where ever damaged /Brocken including basement also.

It was informed during inspection that ground and 7th floor are being renovated.

In view of above shortcomings, the renewal of Fire Safety Certificate cannot be considered. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at risk and liability of owner/occupier. The statuary authority may take, suitable necessary action as deemed fit.

Delhi Fire Service

Copy to:

The Medical Superintendent, LNJP hospital, New Delhi.

2. The Superintendent Engineer (SE), Electrical health & Maintenance, MSO building. Second floor, IP Estate, ITO, New Delhi.

3. The Assistant (Engineer (E)-II, Health Maintenance Electrical Division (Central), PWD (NCTD), Lok Nayak hospital, New Delhi.