

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No. F6 /DFS/MS/Industrial/SZ/2023 / 1291

Dated: 21/06/2023

To.

The Authorized Signatory, M/s Dhingra Auto Cars LLP, A-1, A-1/1, Okhla Industrial Area, Phase-I, New Delhi-20.

Sub: - Regarding renewal of Fire Safety Certificate in r/o M/s Dhingra Auto Cars LLP located at Plot no. A-1, A-1/1, Okhla Industrial Area, Phase-I, New Delhi-20.

Sir,

This has reference to the your email dated 12.06.2023 on the subject cited above, it is informed that the said building was inspected by a team of officers concerned of this department on 15.06.2023 in the presence of Mr. Walter (Load Customer Service) and it was observed that the building is comprised of Two tier Basements + Ground + 05 upper floors. During the inspection following shortcomings were observed:

- 1. Pressurization of lift & staircase found not functional.
- Fire Check Door (FCD's) found removed in one of the staircases at ground, 1st, 2nd & 3rd floor.
- 3. PA System found non functional.
- 4. Vertical openings were found not sealed.
- 5. Water curtain system in car lift found removed.
- 6. Sprinkler heads to be relocated below ventilation ducts.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

(Atul Gara)

Director

Delhi Fire Service

Copy to:-.

The Executive Engineer (Building), South DMC, Jal Vihar, Lajpat Nagar, New Delhi-24.