

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

C-5.
DFA.

NO. F-6/DFS/MS/EH/2023/SZ/339

Dated:-23/06/2023

To.

The Manager,
M/s. Supershot, A unit of Paul Sales Pvt. Ltd.,
A-21/17, Naraina Industrial Area, Phase-2, Naraina, New Delhi- 110028.

Sub: - Regarding issue of "fire safety certificate" from fire safety point of view in r/o M/s. Supershot, A unit of Paul Sales Pvt. Ltd. located at A-21/17, Naraina Industrial Area, Phase-2, Naraina, New Delhi- 110028

Sir,

Please refer to your ID No. 2023032604276 dated 14.06.2023, on the subject cited above. In this connection, it is to inform you that officers concerned of this department inspected the premises on 23.06.2023 to verify the fire safety arrangements in accordance with the rules. At the time of inspection Mr. Arun Kumar (Owner) was present and it was observed that the restaurant building is comprised of basement, ground floor plus three upper floors of building and restaurant is running ground plus three upper floors of building and have following shortcomings.

- 1 Fire Check Door not provided in basement.
- 2 Exit signage not provided.
- 3 Fire Fighting pump not found functional on auto mode.

Keeping in view of above, the building cannot be considered for issuance of fire safety certificate, at this stage. Therefore you are advised to rectify the above said shortcomings under the intimation to this department for further course of action.

Yours faithfully

(Arun Gang)
Director

Delhi Fire Service

Copy to:-

1. The Joint Commissioner of Police, Licensing Unit, First Floor, Police Station, Defence Colony, New Delhi.

de
c b h