



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**

No.F6/DFS/MS/Hospital/2023/WZ/ 1497

Dated 18 / 07/2023

To,

Sh. Mukesh Kumar Gupta Multi-Specialty Hospital Near Bus Stand, Bawana, Delhi -39.

Sub: - Regarding issuance of Fire Safety Certificate in r/o M/s Gupta Multi-Specialty Hospital located at Dhandu Ram Market, Near Bus Stand, Bawana, Delhi -110039.

Sir,

This has reference to your letter received through email dated 07.06.2023 on the subject cited above. In this regard, it is to inform you that the aforesaid hospital building was re-inspected by officer concerned of this department on 30.06.2023 in presence of Dr. D.P. Gupta to verify the fire safety arrangement provided there in. During the course of the inspection it is observed that the building is comprised of ground & 03 upper floors only and the observations/ shortcomings made are as under:-

1. The width of staircase is provided 02m & 01m against the requirement of 02m & 1.50m.

2. Staircases doors are not provided.

Keeping in view of above, issuance of Fire Safety Certificate cannot be considered at this stage & rejected. You are requested to rectify the above mentioned shortcomings under intimation to this department; till such time running of hospital is at your own risk & responsibility.

Yours faithful

Copy to :-

The Director General of Health Services, Nursing Home Cell, 3rd Floor, DGD Building, S-1, School Block, Shakarpur, Delhi-110092.