



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/Industrial/SZ/2023/ 1714

Dated: 16/08/2023

To

Mr. Sumit Kumar (Sr. Executive),
Kent RO System Ltd.,
Plot no. A-3/B-1, MCIE, New Delhi-44.

Sub: - Regarding renewal of Fire Safety Certificate in r/o Plot no. A-3/B-1, MCIE, New Delhi-44.
Sir,

With reference to your letter no. nil dated 20.07.2023 on the subject cited above, it is informed that the said building was inspected by a team of officers concerned from this department on 27.07.2023 in the presence of Mr. Rahul Tiwari (Admin Executive) and it was observed that the building is comprised of Basement + Ground + 3 upper floors. During the inspection the following shortcomings were observed:

1. Hose reel found not functional.
2. Automatic sprinkler system found not functional.
3. Internal hydrant system found not functional.
4. Ground & Terrace level fire pumps found not functional.
5. Overhead tank capacity 15,000 liters provided against the requirement of 20,000 liters.
6. Conveyer from alternate staircase to basement shall be removed/relocated.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,


(Atul Garg)
Director

Delhi Fire Service

etc 16/8/23

Copy to:-

1. The Executive Engineer (Building), South DMC, Jal Vihar, Lajpat Nagar, New Delhi-24.