OF NATIONAL CAPITAL TERRITORY OF DELHI



No. F6/DFS/MS/WZ/EH/2023/ 1857

To,

The Executive Engineer (Bldg.), South Delhi Municipal Corporation, 9th floor, Civic Centre, Minto Road, New Delhi-110002.

Subject: - Regarding Issuance of Fire Safety Certificate in R/o R.G. Stone Urology & Laparoscopy Hospital, Located at B-1, Vishal Enclave, Rajouri Garden, New Delhi- 110027.

Sir,

This is in reference to your letter no. D 410/EE(B)-1/WZ/AE(B) dated 03/08/2023, on the subject cited above. In this connection, it is to inform you that the premises was re-inspected by officer concerned of this department on 22/08/2023 in the presence of Dr. Amit to check the shortcomings already issued by this deptt. vide letter No.- F6/DFS/MS/Hospital/2023/1503 dated: 18/07/2023. However, the status of shortcomings is as under.

0.11	Shortcomings	Status
S. No.	Shortconnings	Not Rectified
1.	Width of staircases in basement is provided 1.45m & 1x 1.70m against requirement of 2 x 1.5m.	Not Rectified
2.	Width of staircases in upper floors is provided 2m, 1.45m & 0.90mtr against requirement of 2 x 1.5mtr & 1 x 2m.	
•	Fire Check Door is not provided at some places.	Not Rectified
3.	Width of corridor is provided 1.78m against requirement of 2.40m.	Not Rectified
4.	Width of corridor is provided 1.76m against requirement of	Rectified
5.	Door size of patient rooms is provided 96cm to 108cm against requirement of	
	1.25mtr & 2mtr.	Rectified
6.	Smoke Management System is not provided.	Rectified
7.	Smoke Detector & Sprinkler System is not provided in Ground floor & 3 rd	
The state of the s	Standby pump capacity of 1620lpm is not provided.	Not Rectified
8.	Standby pump capacity of 1020ipm is not provided against	Not Rectified
9.	Under Ground Water Storage Tank capacity of 20000ltr provided against requirement of 75000 ltr.	
10	Exit Signage's are not provided.	Rectified
10.	Lift lobby is not segregated with Fire Check Door.	Not Rectified
11.	Lift looby is not segregated with the officer poor	

In view of above shortcomings the application for Issuance of Fire Safety Certificate is not considered & rejected. The occupancy of the Building/Premises in absence of requisite fire safety arrangements shall be at the risk and liabilities of the Owner/Occupier. The licensing issuing authority/statutory authority is requested that premises should not be allowed to run till it provide all necessary fire arrangements.

Yours faithfully,

Copy to: -

1. The Medical Superintendent, R.G. Stone Urology & Laparoscopy Hospital, Located at B-Vishal Enclave, Rajouri Garden, New Delhi- 110027.

2. The Director, DGHS, New Karkardooma Court, Anand Vihar, New Delhi 110032.