

C-32

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No.
To

F.6/DFS/MS/School/2023/SZ/ 367

Dated: 31.10.2023

The Principal,
Saraswati Mandir Senior Secondary School,
Ward No -06, Mehrauli New Delhi 110030.

Sub.- Regarding issuance of Fire Safety Certificate in r/o Saraswati Mandir Senior Secondary School, Ward No -06, Mehrauli New Delhi 110030..

Sir,

This has reference to your letter no nil dated 10/07/2023, received through outdoor diary no 4340 Dated 01/08/2023 on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 18/08/2023 in the presence of Mr. Upendra Kumar Shastri. During the inspection it was observed that school is running at ground plus three upper floors. Accordingly fire safety arrangement were tested / checked and found following observation.

1. First aid hose reels provided but found nonfunctional.
2. MOEFA found removed.
3. Public address system found removed.
4. Terrace level fire fighting pumps capacity 360 LPM provided but found not functional.
5. Overhead tank of 5,000 ltrs provided against the required capacity of 10,000 ltrs.
6. Exit signage found removed at some places.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to: -

1. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054