

## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/School/2023/SZ/ 37/

Dated: 31/08 /2023

The HOS / Vice Principal, Veer Chander Singh Garhwali, Govt. Sarvodaya BAL Vidyalaya, J Block, Saket New Delhi

Sub: Reg. renewal of Fire Safety Certificate in r/o Veer Chander Singh Garhwali, Govt. Sarvodaya BAL Vidyalaya, J Block, Saket New Delhi (ID 1923056)

Sir,

This has reference with your letter no VCSG/SBV/Jblk/Saket/2022/23/442 Dated 24/07/2023 on the subject cited above. In this regard, school premises have been inspected by officer concerned of this department on dated 18.08.2023 in presence of Dr. Vijay Kumar Kaushik to verify the status of existing fire prevention and fire safety measures. During the course of inspection, the shortcomings observed are as below;

1. Hose reel found non-functional in old block, (ground plus two) & new blocks ground plus three upper floors two blocks in the building.

Terrace pumps found non-functional in old block, (ground plus two) & new blocks ground plus three upper floors two blocks in the building

The same observation has already been issued and communicated earlier by this department vide letter of even no 213 dated 16.04.2021.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

DIRECTOR

DELHI FIRE SERVICE

Copy to: -

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat Delhi 110054