

C-05

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

NO. F-6/DFS/MS/EH/SZ/2023/ 491

Dated:- 06/09/2023

To,

The Owner/Occupier,  
M/s. Guruprasad Udipi Restaurant,  
10204, GF, Block S, Ward No. 16,  
Padam Singh Road, Karol Bagh, New Delhi- 05.

Sub: - Regarding issuance of fire safety certificate in r/o M/s. Guruprasad Udipi Restaurant, 10204, GF, Block S, Ward No. 16, Padam Singh Road, Karol Bagh, New Delhi- 05.

Sir,

Please refer to online application ID 2023082214969 dated 23.08.2023 on the subject cited above. The above said eating house running at ground floor of a building comprised of basement, ground plus three upper floors. The above said assembly building (Restaurant) was inspected by the officer concerned of this department from safety point of view on dated 01.09.2023 in presence of Sh. Satish Kumar (Manager).

During the course of inspection the following shortcomings have been observed:-

- 1 Two exits found provided with width 1.20 & (1.47 mts. through kitchen area) against requirement of two exit having width of 1.50 mts. each.
- 2 Fire Check Doors are not provided in kitchen.
- 3 Smoke ventilation not provided.
- 4 MOEFA found not provided.
- 5 Terrace pump capacity 450 LPM is not provided.
- 6 Overhead water storage tank capacity of 20,000 lts found not provided.
- 7 Exit signages are not provided at the places mentioned during the inspection.

Keeping in view of above, issuance of fire safety certificate cannot be considered at this stage. You are requested to rectify the above said shortcomings for taking further necessary action in this matter under intimation to this department.

Yours faithfully

  
(Atul Garg)  
Director  
Delhi Fire Service

