



75
Azadi Ka
Amrit Mahotsav

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**

No. F.6/DFS/MS/Metro/2023/NDZ/ 1927

Dated: 06/09/2023

To,

Sh. Vivek Shrivastava (JGM/E&M)
Metro Bhawan, Fire Brigade Lane, Barakhamba Road,
Delhi-110001

Sub:- Regarding Issuance of Fire Safety Certificate in r/o Metro Vihar (Shastri park Staff Quarter at Shastri Park Jagjit Nagar, Delhi-110031

Sir,

With reference to your letter No. DMRC/O&M/Fire/NOC/SQ/Line-1/2023/01/01 dated 23/01/2023 on the subject cited above. In this connection, it is to inform you that the officers concerned of this department has carried out the inspection of the premises from fire safety point of view in presence of Sh. Vikas Bhardwaj, Manager/Fire on dated 24/07/2023. The building comprised of stilt plus seven upper floors (08 Separate Blocks). Following shortcomings were observed during the time of inspection:-

1. Fire Check Door found removed.
2. Electric shaft not sealed.
3. Terrace pump of 450 lpm capacity is provided against the requirement of 900 lpm.
4. Overhead water tank of capacity 5,000 liters provided against the requirement of 25,000 liters.

In view of above, the application for issuance Fire Safety Certificate is rejected. The occupancy of building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

(ATUL GARG)
DIRECTOR

0/c
DELHI FIRE SERVICE