

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS : DELHI FIRE SERVICE, NEW DELHI - 110001

No. F.6/DFS/MS/Business/NDZ/2023/ 200

Dated: 15/09/2023

To

The Executive Engineer (Bldg. Department),
Municipal Corporation of Delhi,
Dr. SPM, Civic Centre, New Delhi-02.

Sub: Regarding issuance of Fire Safety Certificate in respect of **Multilevel Car Parking at Gandhi Maidan, Chandni Chowk, Delhi - 06.**

Sir,

This is in reference to online application ID No.10062504 dated 01.09.2023 on the subject cited above. In this connection, it is to inform you that the joint inspection of the premises was conducted by the team of officers from Delhi Fire Service alongwith Mr. Waqar Ahmad Khan (J.E.) MCD on dated 14.09.2023 to verify the fire safety measures installed in the building and observed that building is comprised of Three Basements, Ground and 04 upper floors. During inspection following shortcoming were observed:

1. Compartmentation is incomplete at some places in basement.
2. Some MOEFA are found broken and non functional.
3. Inspection ladder for terrace tank is not provided.
4. Exit & lift signage not provided at some places.
5. Automatic sprinkler system & detection system needs to be extended in left out areas.
6. Electrical shafts are not sealed at some places in basement.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected.

The applicant is requested to rectify the shortcomings at the earliest for further action.

Yours faithfully,


(Atul Garg)

Director
Delhi Fire Service
Tel: 011-23414000

Copy to:-

1. The Manager,
Multilevel Car Parking at Gandhi Maidan, H. C. Sen Road, Chandni Chowk, Delhi - 06.