

C 70

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/ 562

Dated:-08.11.2023

To,

The Manager
M/S Klick International,
3357, Kaseruwalan Gali Hari Mandir,
Pahar Ganj, New Delhi.

Sub: Issuance of FSC (Fire Safety Certificate) in r/o Klick International located at 3357, Kaseruwalan Gali Hari Mandir, Pahar Ganj, New Delhi.

Sir,

This has reference to ID No. 2023102017571 dated 20.10.2023, on the subject cited above. In this regard, it is to inform you that the site was inspected by the officers concerned of this department on 31/10/23 in the presence of Manager and following shortcomings were observed: -

1. Exhaust fans are not provided.
2. Hose reel found nonfunctional.
3. CO type detectors are not provided as per Gazette Notification dated 27.05.2019.
4. No. of room is mentioned in application form is one where as in building plan 7 room is shown, please clarify the same.

Hence, the is rejected and Fire Safety Certificate (FSC) cannot be renewed at this stage due to above shortcomings. Therefore, you are requested to rectify the above shortcomings and re-submit for further consideration in the matter.

Yours faithfully,


(Atul Garg)
DIRECTOR
Delhi Fire Service

Copy to:

1. Addl. Commissioner of Police(lic), 1st floor, Defence Colony Police Station, New Delhi.