

## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/EH/2023/SZ/63)

Dated: </ /

To

The Addl. Commissioner of Police. Lic Branch, 1st Floor PS Defence Colony, New Delhi 110049

Sub: - Regarding issuance of Fire Safety Certificate in r/o M/s IDLINAMA (A Unit of Paduka Hospitality Pvt ltd) Plot No M-50, First Floor, M Block Market, Greater Kailash Part-II, New Delhi 110048

This has reference to with MHA Portal ID 2023071912821 dated 31/10/2023 Sir, on the subject above. In this connection, it is to inform you that the inspection of the premise was conducted by the officers concerned of this department on 14/11/2023 in the presence of Sh. Praveen Kumar to check the compliance of fire safety arrangements from fire safety point of view and following shortcomings were observed:

- There are two exit door having width of 1.50 mtr & 1.40 mtr (Fire check door found removed with normal doors) against the required width of 1.50 mtr as per UBBL-2016.
- First Aid Hose Reel provided but found nonfunctional 2.

Down comer system found removed.

- Terrace level Fire Pump provided but found nonfunctional. 3. 4.
- Overhead tank capacity 25,000 ltrs found empty.
- The Exit Signage found removed at some locations. 5.
- Temperary Kitchen at terrace level not allowed. 6. 7.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours hithfully,

DELHI FIRE SERVICE