

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



No F 6 / DFS / MS/ 2023/WZ/ 4392

Dated: 07/12/2023

To,

Shri Pursottam Singh, DGM (Operation), Pragati Power Corporation Limited, DSIIDC Industrial Area, Sector-V, Bawana, New Delhi-110039

Sub.:- Inspection report from fire safety and means of escape point of view in r/o Pragati Power Corporation Limited, DSIIDC Industrial Area, Sector-V, Bawana, New Delhi-110039

Sir, Please refer to your letter No. GM (T) PPS-III/F.9/2022-23/2241 dated 17/10/2023 on the subject cited above. In this connection, it is to inform you that the above mentioned premises have been inspected by the officers concerned of this department to check the shortcomings already issued by this department vide letter No, F.6/DFS/MS/2019/4153 dated 12/07/2019. The status of shortcomings is as under:-

Tar tar.	Status
Shortcomings	Not Provided
floor & O and M Store block-Basement+ ground +02 against the requirement of two. The width of second	
Staircase is required 2.55 M store block not provided in	Provided
hasement	provided
Exit signage not provided at some places	provides
	against the requirement of two. The width of second staircase is required 1.35 mts including basement. Sprinkler system in O & M store block not provided in

Keeping in view of the above shortcomings, Fire safety certificate cannot be considered at this stage. You are requested to comply the above shortcomings under intimation to this department, till such time, occupancy of the building at your own risk and responsibility.

Yours faithful