



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/2023/SZ/ 4338
To

Dated: 14/12/2023

Mr. Sakti Perumal (President),
Delhi Tamil Sangam,
Tamil Sangam Marg,
Sector-5, R.K Puram, Delhi 110022

Sub: Regarding issuance of Fire Safety Certificate in r/o Delhi Tamil Sangam, Tamil Sangam Marg, Sector-5, R.K Puram, New Delhi 110022.

Sir,

This has reference with your letter no nil date 29/11/2023, received through outdoor diary no 10202 dated 30/11/2023 on the subject cited above. In this connection, it is to inform you that the inspection of above said building have been carried out by the officer concerned of this department on 08/12/2023 in the presence of Mr. Sakti Perumal and observed to verify the fire safety measures installed in the building. During inspection, following points were observed:

1. Smoke managements system provided but found nonfunctional.
2. First aid hose reel hose provided but found nonfunctional.
3. Automatic sprinkler system provided but found nonfunctional.
4. Internal hydrant & yard hydrants provided but found nonfunctional.
5. Fire fighting pumps capacity 2280 LPM Electrical & Standby pump capacity 900 LPM found removed.
6. Exit signage found removed at some places.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours Faithfully,


(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE
