

c/21

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001

No. F6/DFS/MS/School/2023/SZ/ 583

Dated: 14/12/2023

To,

The Principal,
Indian Convent School,
K-1/72, Peepal Wala Road,
Mohan Garden, New Delhi-110059

Sub:- Regarding Issuance of Fire Safety Certificate in r/o Indian Convent School, K-1/72, Peepal Wala Road, Mohan Garden, New Delhi-110059.

Sir,

This is in reference to your letter No. Nil dated 26/10/2023 on the subject cited above. In this connection, it is to inform you that the inspection of above said building has been carried out by officer concerned of this department on 11/12/2023 in presence of Sh. Anoop Kumar. During the course of inspection it was observed that the building is comprised of ground plus one floor. The following shortcomings were observed:-

1. One staircase is found blocked.
2. Fire extinguishers provided but not functional.
3. Exit signage's provided but not sufficient.

Keeping in view of above, the building cannot be considered for issuance of fire safety certificate, at this stage. Therefore you are advised to rectify the above said shortcomings under the intimation to this department for further course of action.


Yours Faithfully



(Atul Garg)

Director

Delhi Fire Service



Copy:-

The Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
New Delhi-110054.