

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No. F6 /DFS/MS/Industrial/SZ/2021 41

Dated: 08 01 2024

To,

The Owner/occupier/manager,
M/s Pascos Hospitality Pvt. Ltd,
Plot No.B-1/1-3-1, MCIE, Mathura Road, New Delhi.

Sub: - Regarding renewal of Fire Safety Certificate in r/o M/s Pascos Hospitality Pvt. Ltd, located at Plot No.B-1/1-3-1, MCIE, Mathura Road, New Delhi.

Sir,

With reference to the your Email dated 27.12.2023 on the subject cited above, it is informed that the said building was inspected by a team of officers concerned of this department on 03.01.2024 in the presence of Mr. Manoj Kumar (Manager) and it was observed that the building is comprised of Basements + Ground + 02 upper floors. During the inspection following shortcomings were observed:

- 1. Fire check door (FCD) found removed.
- Pressurization system is not as per standards and same needs to be synchronized with ADAS & MOEFA.
- 3. Hydrant pump is 1620 LPM provided against the requirement of 2280 LPM.
- One of the riser landing valves & hose reel system found hidden in a cabinet inside occupied area.
- 5. Lift lobby found not provided.
- 6. Exit signages found removed.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Director

Delhi Fire Service

Copy to:-.

1. The Executive Engineer (Building), South DMC, Jal Vihar, Lajpat Nagar, New Delhi-24.