

DFA

c/3

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI - 110001**

No.F.6/DFS/MS/SZ/2024/09

Dated: - 10/01/2024

To,

The Principal,
Grandmothers arms pre primary School,
RZP-6, Raj Nagar, Part-2, New Delhi-110077.

Subject: Issuance of Fire Safety Certificate in r/o Grandmothers arms pre primary School Located at RZP-6, Raj Nagar, Part-2, New Delhi-110077.

Sir,

Please refer to your Email dated 14/12/2023 on the subject mentioned above. In this connection it is to inform you that the premises visited by the officer concerned of this department on 02/01/2024 in the presence of Mr. Ashish from fire safety point of view.

During the course of inspection followings shortcoming have been observed:-

1. One staircase of 136 cm width found provided against required two staircases of 1.5 m clear width *each*.
2. Width of class room doors found varies from 80 cm to 100cm, all the class room doors must have 100 cm clear width.
3. Width of the corridor/ passage leads to staircases/ Exists must not be less than 1.5mtr.
4. Hose reel hose found not provided.
5. Terrace pump of 450 lpm capacity found not provided.
6. Overhead fire water tank of 10000 ltr capacity found not provided.
7. Exit signage found not provided at some places.
8. Dully fill form J & School details form are not submitted

In view of the above shortcomings issuance of Fire Safety Certificate from fire safety point of view cannot be considered at this stage. You are directed to comply the shortcomings under intimation to this department for further consideration in the matter.

Yours faithfully,


(Atul Garg)

Director
Delhi Fire Service

o/c 

Copy to; - Directorate of Education Old Secretariat Delhi - 110054.