

(-8

GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE Dated: 17 01 /2024 **NEW DELHI- 110001**

F.6/DFS/MS/GH/2024/SZ/ 2 2 No. To

The Joint Commissioner of Police, Lic/Branch, 1st Floor, P.S Defence Colony, New Delhi 110049

Regarding issuance of FSC in r/o M/s GLORY located at Kh. No 410, Road No-4, Sub: Street No 7, Mahipalpur New Delhi 110037

This has reference with MHA Portal ID 2023120819373 Dated 19/12/2023 on Sir, the subject cited above. In this connection, the premises have been inspected by officer concerned of this department on 16/01/2024 in the presence of Ms. Jiya (Manager) of the Guest House. Accordingly fire safety arrangement were tested / checked and found following observation.

1. There are two staircase having with of 1.50 mtr & 1.35 mtr against the required

2. The width of corridor is 1.35 mtr against the required width shall be 1.50 mtr for single loaded and 1.80 mtr for double loaded as per clause 7.11.2 of UBBL 2016.

3. Smoke ventilation system not provided in the building as per clause 7.31 of UBBL 2016.

4. First aid hose reel provided but found not functional.

5. Carbon Monoxide detector not provided as per clause 7.31 of UBBL 2016.

6. Internal hydrant system not provided.

7. Terrace level pumps capacity 450 LPM not working.

8. Overhead tank capacity 6000 ltrs provided against the required capacity of 10,000 ltrs & fire fighting tank are not dedicated.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

DELHI FIRE SERV