



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/2024/Indl./ **153**

Dated **25** /01 /2024

To

The Authorized Signatory
Sharp Mint Ltd. at C-3, SMA, Co-Operative,
G.T. Karnal, Industrial Area, Delhi-110033.

Sub: Regarding issuance of Fire Safety Certificate in r/o Sharp Mint Limited located at C-3, SMA, Co-Operative, G.T. Karnal, Industrial Area, Delhi-110033.


Sir,

Please refer to your letter no. nildated 10.01.2024 on the subject cited above. In this connection this is to inform you the above mentioned site was visited by the officer concerned of this department on 20.01.2024 to verify the fire safety arrangements installed in the building as per issued fire safety recommendations vide letter of even no F6/DFS/MS/BP/2023/12 dated 03.01.2024. At the time of inspection Sh.Mukesh Yadav (Attendant) was also present at site. During the course of the inspection, it is observed that the building is comprised of ground & two upper floors only. Your request for FSC is rejected under Rule 37 (3) due to following shortcomings.

1. There are two staircases provided width of 1.20m each against the requirements of 1.50m each and both staircases required from ground to terrace level.
2. Fire check doors not provided.
3. The doors size of 01m provided against the requirements of 1.50m in staircase.
4. Smoke ventilation system is not provided in the building.
5. Hose reel hose is provided but not functional
6. Smoke detector is not provided.
7. Manually operative fire alarm system is provided but not functional.
8. Sprinkler systems is not provided at 1st floor & 2nd floor in the building.
9. Internal hydrant & yard hydrant is provided but not functional.
10. Terrace level fire pump capacity of 900 lpm is provided but found not functional.
11. Terrace level fire water tank capacity of 10,000ltr is provided against the requirement of 50,000ltr.
12. Exit signage's and floor signage is not provided at strategic location in the building.

Keeping in view of above, issuance of Fire Safety Certificate cannot be considered at this stage & rejected. You are requested to rectify the above mentioned shortcomings under intimation to this department; till such time running of industry is at your own risk & responsibility.

Yours faithfully


(Aul Garg)
Director

Ph:-011-23414000

Copy to:-

1. The Dy. Commissioner of Factory licensing, SIDMC 3rd, Floor, Civic Centre
Minto Road, Delhi-110002.