

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



C-42

No: F.6/DFS/MS/School/2024/W// 46

Dated: 08/02/2024

To,

The Principal,
Sarvodaya Kanya Vidyalaya,
Tulsi Nagar, Delhi-110034.

Sub: - Regarding issuance of Fire Safety Certificate in r/o Sarvodaya Kanya Vidyalaya located at Tulsi Nagar, Delhi-110035.

Sir,

This has reference to your email id dated 18.01.2024 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 31.01.2024 to check the shortcomings already issued by this department vide letter No. F.6//DFS/MS/School/2015/1393 dated 26.06.2015, Dr. R.K. Jaiswal (Principal) was present at the time of inspection.

During the course of inspection it was observed that school building is comprised of 02 Blocks interconnected in H shape, 01 Block (Ground plus First Floor) and 01 Block (Ground plus Three upper floors). Your request for issuance of FSC is rejected due to the following shortcomings:-

1. First aid hose reels provided but not functional.
2. Terrace level pump found provided but not functional.
3. Exit signage's not provided.
4. Electric wiring should be in metal conduit/ concealed type.

In view of the above complaints, fire safety certificate cannot be considered at this stage. You are advised to rectify the above-mentioned shortcomings under intimation to this department.

Yours Faithfully


(Atul Garg)
Director

Ph. 011-23414000

Copy to:-

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi-54.