



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2024/BB/46

Dated: 14/02/2024

To,

The Authorized Signatory
Plot No. A-21-22, Savitri Bhawan,
Commercial Complex, Dr. Mukherjee Nagar, Delhi-09.

Sub:- Regarding issuance of Fire Safety Certificate in r/o Plot No. A-21-22, Savitri Bhawan,
Commercial Complex, Dr. Mukherjee Nagar, Delhi-110009.

Sir,

Please refer to your letter received through online E-mail dated 31.01.2024 on the subject cited above. In this connection this is to inform you the above mentioned site was visited by the officer concerned of this department on 06.02.2024 to verify the fire safety arrangements installed in the building. At the time of inspection Sh. Tilak Raj Bhatia (Attendant) was also present at site. During the course of the inspection it is observed that the building is comprised of basement (sealed by MCD), ground, mezzanine & 03 upper floors only. Your request for FSC is rejected under Rule 37 (3) due to following shortcomings.

1. Fire check doors found removed.
2. Hose reel hose provided but not functional.
3. Automatic fire smoke detector system found removed.
4. Public Address System found removed.
5. Internal hydrant provided but not functional.
6. Terrace level fire pump capacity of 450lpm provided but not functional.
7. Terrace level fire water tank 15,000ltr provided against the requirement of 50,000ltr.
8. Standby power supply found removed.
9. MCB electrical box are installed inside the stairwell, which need to be removed.

Keeping in view of above, grant of Fire Safety Certificate cannot be considered at this stage & rejected. You are requested to rectify the above mentioned shortcomings under intimation to this department; till such time running of building is at your own risk & responsibility.

Yours faithfully


(Atul Garg)
Director

Ph: 011-23414000


12/2