

c/66



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/EH/2024/SZ/ 63

Dated: 12/02/2024

To  
The Dy. Health Officer, MCD,  
Public Health Department, Green Park Zone,  
Aurobindo Marg, New Delhi 110016.

Sub: Regarding issuance of Fire Safety Certificate in r/o M/s EBISU (Unit of VV Restaurant Pvt Ltd) at Shop No.-11, 12, 13 & 14, Ground Floor, Salcon Tower, Rasvilas Saket, New Delhi- 110017

Sir,

This has reference with **MHA Portal ID 2024011900613 & 2024011900624 & 2024011800600 dated 19/01/2024** on the subject cited above. In this concerned, it is to inform you that the premise was inspected by the concern nominated authority of this department on 02/02/2024 in presence of Mr. Ramesh Kumar to verify the fire safety measures installed in the building. Accordingly fire safety arrangement were tested / checked and found following observation.

1. The width of corridor is 1.20 mtr against the required width of 1.50 mtr.
2. The Main exit door is sliding door which is not allowed.
3. The Exit Signage not provided
4. Electrical installation / meter found installed in the escape routes near staircases, which is not acceptable.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

  
**(ATUL GARG)**  
**DIRECTOR**  
**DELHI FIRE SERVICE**