GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F.6/DFS/MS/NDZ/2024/ 6

Dated:-1.9.152/2024

To,

Administrator, Major Dhyan Chand National Stadium, New Delhi.

Sub:- Regarding renewal of FSC in r/o Major Dhyan Chand National Stadium, New Delhi. Sir,

This has reference to your mail id no.mdcns-sai@gov.in dated 09.01.2024, on the subject cited above. In this regard, it is to inform you that the site was re-inspected by the officers concerned of this department on 07/02/2024 in the presence of Mr. Pankaj (Electrician), and the following shortcomings were observed:-

- 1. 02 Staircases were found blocked.
- 2. Fire check door found broken at some places.
- 3. Detectors are not provided in AHU/ electrical room and also found nonfunctional in other area.
- 4. Office Corridor found encroached by dumping of almirah.
- 5. Smoke management in basement found nonfunctional.
- 6. MOEFFA found nonfunctional.
- 7. Hydrant couplings & hoses found missing from hose boxes.
- 8. Hose reels found nonfunctional and nozzles found broken/removed at some places.
- 9. PA system is not audible properly at some locations.
- 10. Sprinkler system found nonfunctional and covered under false ceiling.
- 11. Flow switch panel and detector panel found nonfunctional in fire control room.
- Exit signages found inadequate.
- 13. Lift signages found not provided.

Therefore, you are requested to rectify the above shortcomings at the earliest under intimation to this department. Further, the occupancy of building /premises in absence requisite fire & life safety arrangements shall be at the risk and liability of the owner/occupier. The statuary/licensing authority may take suitable action as deemed fit.

Atul Garg)
DIRECTOR
Delhi Fire Service

Yours flither

Copy to:-

- 1. The Executive Engineer (E), SAI Maintenance Division, CPWD, IGI stadium, New Delhi
- 2. The Assistant Engineer (E), SAIMED, CPWD, MDC National Stadium, New Delhi.