



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

CMY

No: F.6/DFS/MS/School/2024/WZ/82

Dated: 26/02/2024

To,
The Principal,
Govt. Sarvodaya Kanya Vidyalaya, No.1,
Keshavpuram, Delhi-110035.

Sub: - Regarding issuance of Fire Safety Certificate in r/o Govt. Sarvodaya Kanya Vidyalaya, No.1 located At Keshavpuram, Delhi- 110035.

Sir,

This has reference to your application No. 1831 dated 03.02.2024 received via outdoor diary number 12663 dated 05.02.2024, on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 21.02.2024 to check the shortcomings already issued by this department vide letter No. F6/DFS/MS/School/WZ/2022/77 dated 23.02.2022, Mrs. Neeru Prabhakar (Vice Principal) was present at the time of inspection.

During the course of inspection it was observed that school building is comprised of 02 Blocks, 01 Block (Ground plus Three upper floors) and 01 Block (Ground plus first floor). Your request for issuance of FSC is rejected due to the following shortcomings:-

1. Width of staircases in G+3 block found 1.30 m each against the required width of 1.50 m each and in G+1 block only single staircase of 1.40 m width found provided against the requirement of 02 staircase of 1.50 m each.
2. First aid hose reels provided but not functional.
3. Terrace level pump found provided but not functional.
4. Exit signage's not provided.
5. Electric meter and electrical panel found installed in corridor which have to be removed or segregated from the corridor.

In view of above complaints, fire safety certificate cannot be considered at this stage. You are advised to rectify the above-mentioned shortcomings under intimation to this department.

Yours Faithfully

(Atul Garg)
Director
Ph. 011-23414000

29/2/24

Copy to:-

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi-54.