

GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI- 110001**

F.6/DFS/MS/GH/2024/SZ/123 No.

Dated: 27../03.../2024

To

The Addl. Commissioner of Police, Lic/Unit, 1st Floor, P.S Defence Colony New Delhi 110049.

Sub: Regarding issuance of FSC in r/o M/s Hotel Luxury Stay at Kh. No- 552, Mata Chowk, Mahipalpur, New Delhi -110037

Sir.

This is in reference with MHA Portal Id 2024030402513 dated 05/03/2024 on the subject cited above. In this connection, the premises have been inspected by officer concerned of this department on 20.03.2024 in the presence of Mr. Aman of the Guest House. During the inspection, it was observed that the Guest House is running First, Second & Third Floor. The shortcomings observed are as below:

Fire Check Door not provided as per clause 7.31 of UBBL 2016

2. Smoke management system not provided as per clause 7.31 of UBBL 2016.

3. Carbon Monoxide detector not provided as per clause 7.31 of UBBL 2016.

Exit Signage not provided.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit. Yours mithfull