

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F.6/DFS/MS/2024/NDZ/college/56

Dated 27/03/2024

To,

Mr. Narinder Singh,
The Indian Society of International Law,
V.K. Krishna Menon Bhawan, 9,
Bhagwan Dass Road, New Delhi-01.

**Sub:- Regarding issuance of FSC in r/o M/S The Indian Society of International Law,
V.K. Krishna Menon Bhawan, 9, Bhagwan Dass Road, New Delhi-01.**

Sir,

This has reference to your letter no. ISIL/Admn./2024/02 dated 05.03.2024, on the subject cited above, it is to inform that the site was inspected by the officers concerned of this department on 14.03.24 in the presence of Mr. Ravinder, care taker and the following shortcomings were observed:

1. Alternate exit found blocked at third floor.
2. Hydrant coupling and nozzle found missing at some places.
3. Hose reel and hydrant is not provided in basement having library.
4. Smoke management system found nonfunctional in basement.
5. Electrical shafts are not sealed properly.
6. PA system is not audible properly.
7. MOEFA found nonfunctional.
8. Detectors found nonfunctional at some offices and also not provided in some office, required to be provided in left out area.
9. Pumps not in auto start provision.
10. Terrace tank found empty.
11. Exit signages and lift signages not provided.
12. Further sanction building plan is required to be submitted to ascertain the applicability of firefighting arrangement.

Therefore, you are requested to rectify the above shortcomings at the earliest under intimation to this department. Further, the occupancy of building /premises in absence requisite fire & life safety arrangements shall be at the risk and liability of the owner/occupier. The statutory/licensing authority may take suitable action as deemed fit.

Yours faithfully,

(Anil Garg)
DIRECTOR

Delhi Fire Service

Copy to:-

The Chief Architect, NDMC, Palika Kendra, New Delhi.