

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001**

No. F6/DFS/MS/NDZ/2024/ 155

Dated:- 27.03.2024

To

The Dy. Chief Engineer,  
Engineering Department,  
Northern Zonal office, 2<sup>nd</sup> floor,  
25, K.G. Marg, New Delhi – 110001.

Sub: **Regarding of NOC/FSC in r/o Jeevan Deep Building, 10 Parliament Street, New Delhi.**

Sir,

This has reference to your letter No. NZO/ENGG/JB/FIRE/NOC dated 04/03/2024, on the subject cited above. In this regard, it is to inform you that the site was inspected by the officer concerned of this department on 19/03/2024 in the presence of Smt. Mohini Gautam, AE & Sh. A.S. Rawat EE and the following shortcomings were observed.

1. Alternate staircase is not available at 1<sup>st</sup> floor for the occupants of Department of Finance.
2. MOEFA & PA system provided but found nonfunctional.
3. Some fire check doors found removed and replaced with normal door.
4. Detectors found nonfunctional and not provided at some offices.
5. Hose reel nozzle and hydrant coupling found missing at some places.
6. Hoses are found removed from some hose boxes.
7. Opening & Electrical shafts are not sealed properly.
8. Hydrant and hose reel not covering entire area i.e Nehru yuva Centre and Indian oversea bank.
9. Reception is not allowed in lift lobby.

In view of above, the request for issuance of fire safety certificate FSC is rejected. The occupancy of building /premises, in absence requisite fire & life safety arrangements, shall be at the risk and liability of the owner/occupier. The statutory/licensing authority may take suitable action as deemed fit.

Yours faithfully,

  
(Atul Garg)  
DIRECTOR  
Delhi Fire Service

Copy to:-

1. The Chairman , NDMC, Palika Kendra, New Delhi.
2. The Estate Manager, Jeevan Deep Building, 10, Sansad Marg, New Delhi.