

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE**  
**NEW DELHI- 110001**

No. F.6/DFS/MS/School/2024/SZ/ 132

Dated: 22/03/2024

To

The Principal,  
Sarvodaya Vidyalaya No-3,  
Sector-7, R.K Puram, New Delhi 110022.

Sub: Regarding issuance of FSC in r/o M/s Sarvodaya Vidyalaya No-3, Sector-7, R.K Puram, New Delhi 110022

Sir,

This has reference to your letter no. SV/No-3/S-7/RKP/785 dated 19/02/2024 on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 14.03.2024 in the presence of Ms. Anamika (Principal) to verify the fire safety measures installed in the building. Accordingly fire safety arrangement were tested / checked and found following observation.

1. Terrace level Fire Pump capacity of 450 LPM found removed.
2. Overhead tank capacity 10,000 ltrs found removed.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,

(ATUL GARG)  
DIRECTOR  
DELHI FIRE SERVICE