

C-37

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No: F.6/DFS/MS/School/SZ/2024/ 174

Dated: - 18/04/2024

To,

The Principal,
Saraswati Bal Mandir Sr. Sec. School,
J-8 Block, Rajouri Garden, New Delhi- 110027.

Sub.: - Regarding issuance of Fire Safety Certificate in r/o Saraswati Bal Mandir Sr. Sec. School at J-8 Block, Rajouri Garden, New Delhi- 110027.

Sir,

With reference to your letter No. sbm/rg/fire/2023-24/3088 dated 12.03.2024, on the subject cited above. In this connection, it is to inform you that the aforesaid school building have been inspected by the officer concerned of this department on 03.04.2024 in the presence of Mrs. Bela Mishra (Principal), to check the fire safety arrangements provided in the school building.

During the course of inspection, it was observed that the school building is comprised of ground floor plus three upper floors. Fire safety arrangements such as hose reel, fire extinguishers etc. found provided in the school building. However, the following shortcomings were observed: -

1. Temporary structure (4 class room) made at third floor should be removed.
2. First aid hose reel provided 02 Nos. at each floor but found not functional.
3. Terrace fire pump capacity of 450 LPM & 180 LPM found provided but not functional in auto mode.
4. Exit signage found not provided.

In view of the above, renewal of 'Fire Safety Certificate' cannot be considered at this stage. You are requested to rectify the above-mentioned shortcomings under intimation to this department for further necessary action in the matter.

Yours faithfully


(Atul Garg)
Director
Delhi Fire Service


Copy to: -

The Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
New Delhi- 110054.

For information please.