5-3

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI – 110001

OFA FT

NO. F6/DFS/MS/SZ/2024/ C.C/69

DATED: 19 /04/2024

To,

The Executive Engineer (Building). Nigam Bhawan, Anand Parbat, D.B Gupta Road, Karol Bagh, New Delhi – 110005.

Subject: - Issuance of Fire safety Certificate from fire safety & means of escape point of view in r/o Coaching center Located at Plot No. 57/17, 1st&2nd floor, Bara Bazar, Old Rajinder Nagar, New Delhi.

Sir,

Please refer to letter No. D/EE(B)/KBZ/2024/164, dated 15/03/2024 on the subject cited above. In this connection it is to inform you that the above said building has been inspected by the officers concerned of this department on 13/04/2024 in presence of Sh. Ravinder Jha (Owner of Institute) from fire safety point of view.

During the course of inspection followings shortcoming have been observed:-

- 1. Only one staircase is provided for upper floors and basement against required two staircases of 1.5m clear width.
- 2. The width of class room doors are found 78 cm against required 1m clear width.
- 3. Fire Check Door found not provided in basement.
- 4. Smoke management system in basement found not provided.
- 5. Hose reel hose system found not provided.
- 6. MOEFA & PA system found not provided.
- 7. Automatic sprinkler system found not provided in basement.
- 8. Terrace pump of capacity 900 lpm found not provided.
- 9. Over head fire water tank of 15000 ltrs capacity found not provided.
- 10. Exit signage found not provided at some places.

In view of the above shortcomings issuance of Fire Safety Certificate cannot be considered at this stage. You are requested to comply the above mentioned shortcomings under intimation with this department for further consideration in the matter.

Delhi Fire Service

Copy to:- The Owner/Occupier, Coaching center Located at Plot No. 57/17, 1st &2nd floor, Bara Bazar, Old Rajinder Nagar, New Delhi.