

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI- 110001**

No. F.6/DFS/MS/School/2024/SZ/ 213
To

Dated: 02/05/2024

The Principal,
M/s Andhra Education Society,
Dr. K Ramesh Babu Memorial Sr. Sec. School,
Sector -VII, Pushp Vihar New Delhi 110017

Sub: Regarding issuance of FSC in r/o M/s Andhra Education Society, Dr. K Ramesh Babu Memorial Sr. Sec. School, Sector -VII, Pushp Vihar New Delhi 110017

Sir,

This has reference to your Email Dated 01/04/2024 on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 25.04.2024 in the presence of Mr. Ashwathi KE (HOS) to verify the fire safety measures installed in the building. Accordingly fire safety arrangement were tested / checked and found following observation.

1. First Aid hose reel provided but found non-functional.
2. Automatic sprinkler system provided but found non-functional.
3. Internal hydrant provided but fund non-functional.
4. Terrace level fire fighting pumps capacity 450 LPM provided but found non-functional.
5. Exit signage found removed at some places.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,


(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE