GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI – 110001

NO. F6/DFS/MS/SZ/2024/CC 80

DATED: 01 /05/2024

To,

The Executive Engineer (Building). Nigam Bhawan, Anand Parbat, D.B Gupta Road, Karol Bagh, New Delhi – 110005.

Subject: - Issuance of Fire safety Certificate from fire safety & means of escape point of view in r/o Coaching center Located at 1st, 2nd & 3rd floor Plot No. 33 Pusa Road, Karol Bagh, New Delhi.

Sir,

Please refer to your letter No D/EE(B)/KBZ/2024/163. dated 15/03/2024 on the subject cited above. In this connection it is to inform you that the above said building has been inspected by the officer concerned of this department on 19/04/2024 in presence of Sh. Mujassam Nazar from fire safety point of view.

During the course of inspection followings shortcoming are observed:-

- 1. Only one staircase of width 152 cm found provided in basement against required 02 staircase of 1.5 m clear width.
- 2. The 1.5m wide Passage to stairs/ exits found not provided/ obstructed/ not clear.

3. Fire Check Doors found not provided in basement

4. Two exit doors of 1m clear width not provided for each class room where students are more than 45.

5. Smoke management system in basement found not provided.

- 6. Dimension of Underground tank of 150000 ltr capacity not submitted.
- 7. Overhead fire water tank of 10000 ltr capacity not provided.

8. Exit Signage found not provided at some places.

9. Communication system in lift car found not provided.

In view of the above shortcomings issuance of Fire Safety Certificate from fire safety point of view cannot be considered at this stage. You are requested to comply the above mentioned shortcomings under intimation to this department for further consideration in the matter.

Delhi Fire Service

Copy to:-

 The Owner/Occupier, Coaching center Located at 1st, 2nd & 3rd floor Plot No. 33 Pusa Road, Karol Bagh, New Delhi.