

c/43

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No: F.6/DFS/MS/School/SZ/2024/ 264

Dated: - 21/05/2024

To,

The Principal,
Govt. Girls Sr. Sec. School,
Shiv Vihar, New Delhi- 110059.

Sub.: Regarding renewal of Fire Safety Certificate in r/o Govt. Girls Sr. Sec. School (Id-1618193) at Shiv Vihar, New Delhi:- 110059.

Sir,

With reference to your letter No. GGSSS/SV/24-25, dated 29.04.2024, on the subject cited above. In this connection, it is to inform you that the aforesaid school building have been inspected by the officer concerned of this department on 10.05.2024 in presence of Smt. Suman (Principal) to check the fire safety arrangements provided in the school building.

During the course of inspection, it was observed that the school having four blocks namely A, B & C block are comprised of ground plus one upper floor and new building SPS block is comprised of ground plus three upper floors. However, the following shortcomings were observed:-

1. First aid hose reels found provided but not functional in SPS block.
2. Terrace fire pump capacity of 450 LPM found provided but not functional in SPS blk.
3. Exit signage found not provided.

In view of the above, renewal of 'Fire Safety Certificate' cannot be considered at this stage. You are requested to rectify the above-mentioned shortcomings under intimation to this department for further consideration in the matter.

Yours faithfully


(Atul Garg)

Director
Delhi Fire Service

Copy to: -

The Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
New Delhi- 110054 .

For information please.