

C64

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI- 110001

No. F.6/DFS/MS/GH/2024/SZ/236
To

Dated: 16.05.2024

The Addl. Commissioner of Police,
Lic/Branch, 1st Floor, P.S Defence Colony,
New Delhi 110049.

Sub: Regarding issuance of FSC in r/o M/s Capital Hills Situated at C-42, Greater Kailash-I, New Delhi 110048.

Sir,

This has reference with **MHA Portal ID 202404040248** dated **21/05/2024** on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 09.05.2024 in the presence of Ms. Priyanka Sharma to verify the fire safety measures installed in the building. As per earlier MHA portal ID 2022101819236 dated 20/10/2022, the occupancy per floor was 07 Rooms with 09 beds at 1st floor & 08 Rooms & 09 Beds. Now the occupier of per floor is more than of 10 beds. Accordingly fire safety arrangement were tested / checked and found following observation.

1. Fire check doors not provided in the building as per clause 7.31 of UBBL 2016.
2. Smoke management system found removed.
3. Carbon Monoxide detector found removed in the some rooms.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)
DIRECTOR

DELHI FIRE SERVICE

sh me